




Protective Counter Barrier

Product Parts

1. Frame (x1)
2. Feet (x2)
3. Optional Graphic (x1-Top)(xBottom)
4. Hook & Loop Strips



Display Set-Up

Step 1

Remove protective film covering the clear part of barrier. DO this by peeling back from any corner. Dispose of protective film.

Step 2

If your display was ordered with graphics (3), adhere the graphic(s) to bottom and top of frame centered between the sides. Graphic(s) (3) are intended to go on *front of frame.


*Front of frame is identified as non-routed edge and where frame is flush with clear window.

Step 3

Attach Feet (2) to frame by aligning slots, pushing both Frame (1) and foot together until each stops.

Optional Vertical Mount

Remove feet (2) and use Hook & Loop (4) to mount to vertical surface. Place Hook & Loop wherever most useful for your application.



Storage & Care

To Store: Remove feet and store flat in a cool dry place.

To Clean Frame and Feet: Use soap and water.

To Clean Clear Window: Use soap and water, or hydrogen peroxide and isopropyl alcohol-based sanitizers. **DO NOT USE** cleaners or disinfectants containing **Ammonia, Bleach or Alcohol**. Cleaners or disinfectants containing **Ammonia, Bleach or Alcohol** will crack or fog the clear sheet.

Please go to Showdowndisplays.com to find this product and its list of approved cleaners.